

BRAND	PART #	QTY	DESCRIPTION	UNIT REPLACEMENT COST USD	TOTAL REPLACEMENT COST
Manuli	H10095010	1811	GOLDENISO/28 -06	\$3.05	\$5,523.55
Manuli	H10095012	2475	GOLDENISO/28 -08	\$3.12	\$7,722.00
Manuli	H10095019	1146	GOLDENISO/28 -12	\$4.23	\$4,847.58
Manuli	H10095025	1199	GOLDENISO/28 -16	\$5.70	\$6,834.30
Manuli	H10095031	179	GOLDENISO/28 -20	\$8.35	\$1,494.65
Manuli	H10096010	779	GOLDENISO/35 -06	\$4.09	\$3,186.11
Manuli	H10096012	3225	GOLDENISO/35 -08	\$4.14	\$13,351.50
Manuli	H10096019	1345	GOLDENISO/35 -12	\$4.89	\$6,577.05
Manuli	H01059019	855	EQUATOR/1 -12	\$3.49	\$2,983.95
Manuli	H10044038	259	ROCKMASTER/4SH -24	\$10.04	\$2,600.36
Manuli	H10031010	363	ROCKMASTER/12 -06	\$3.13	\$1,136.19
Manuli	H10031012	403	ROCKMASTER/12 -08	\$3.20	\$1,289.60
Manuli	H10031051	66	ROCKMASTER/12 -32	\$11.51	\$759.66
				Total USD	\$58,306.50

**REPLACEMENT COSTS ARE SHOWN FOR REFERENCE ONLY**  
**THE SUPPLIER IS LOOKING FOR REASONABLE OFFERS ON THIS LOT**  
**MILLIONS MORE AT 35% - 60% DISCOUNT ON OUR WEBSITE**  
**DOES YOUR VENDOR GIVE YOU EXTRA DISCOUNTS?? - WE DO!!**  
**ALL PRODUCT GUARANTEED!!**  
**MAKE OFFERS!!**  
**THIS LOT TO BE SOLD AS A LOT**