

LOT3424 AEROQUIP AQP HOSE JAN2020

	A	B	C	D	E	F	G
1	Mfg.	Part No.	Qty - Ft	List (ft.)	Unit Replaceme nt cost	Total replacement cost	
2	Aeroquip	FC234-05	3400	\$29.19	\$5.84	\$19,849.20	
3	High Temperature Fuel and Oil. Fire resistant USCG/MMT, NMMA/BIA.						
4	Aeroquip	FC699-04	42000	\$9.38	\$1.88	\$78,792.00	
5	High Temperature Fuel and Oil. AQP lightweight engine hose.						
6	Aeroquip	FC699-08	2200	\$12.05	\$2.41	\$5,302.00	
7						\$103,943.20	
8	High Temperature Fuel and Oil. AQP lightweight engine hose.						
9	All hose has an AQP elastomer tube. - NO SHELF LIFE LIMITS!!!						
10							
11	REPLACEMENT COSTS ARE SHOWN <u>FOR REFERENCE ONLY</u>						
12	THIS LOT CAN BE PURCHASED IN WHOLE OR PART						
13	MILLIONS MORE AT 35% - 60% DISCOUNT ON OUR WEBSITE						
14	DOES YOUR VENDOR GIVE YOU EXTRA DISCOUNTS?? - WE DO!!						
15	ALL PRODUCT GUARANTEED!!						
16	MAKE OFFERS!!						
17	THE SUPPLIER IS LOOKING FOR REASONABLE OFFERS ON YOUR SELECTION OF THIS STOCK						
18	MINIMUM ORDERS APPLY						
19	MAKE AN OFFER!!						