

LOT 4030 AEROQUIP JAN. 2023 - DEADSTOCK BROKER

	A	B	E	F
1	PART #	QTY	UNIT REPLACEMENT COST USD	TOTAL REPLACEMENT COST USD
2	AERQ_1BA16FJB16	741	\$43.31	\$32,089.29
3	AERQ_1BA12FJB12	583	\$30.65	\$17,866.05
4	AERQ_1BA20FJA20	260	\$64.27	\$16,711.33
5	AERQ_1BA16FJA16	324	\$40.98	\$13,277.26
6	AERQ_1BA12FJA12	474	\$27.55	\$13,057.43
7	AERQ_1B16FLB12	452	\$27.67	\$12,507.07
8	AERQ_1BA20FR20	153	\$56.60	\$8,659.31
9	AERQ_1B20FLB20	198	\$43.24	\$8,561.62
10	AERQ_1BA20FJB20	133	\$63.14	\$8,398.18
11	AERQ_1BA16FJB12	132	\$53.78	\$7,098.71
12	AERQ_1Z24FHA24	70	\$94.55	\$6,618.61
13	AERQ_1BA12MP12	777	\$7.90	\$6,139.68
14	AERQ_1B20FL20	170	\$31.61	\$5,374.08
15	AERQ_1BA24FJB24	39	\$125.55	\$4,896.45
16	AERQ_1B20FLA20	106	\$43.23	\$4,581.96
17	AERQ_1BA16FR16	154	\$27.72	\$4,268.47
18	AERQ_1BA24FJA24	39	\$105.56	\$4,116.91
19	AERQ_1BA16FRB16	109	\$36.59	\$3,987.91
20	AERQ_1BA16FRA16	95	\$41.57	\$3,949.47
21	AERQ_1BA20FJC20	39	\$101.18	\$3,946.14
22	AERQ_1BA20FRA20	71	\$54.01	\$3,834.63
23	AERQ_1BA20FJ16	103	\$35.67	\$3,673.96
24	AERQ_1EA16FRB16	64	\$56.23	\$3,598.52
25	AERQ_1BA20FRB20	46	\$73.60	\$3,385.68
26	AERQ_1B20FLA16	76	\$39.56	\$3,006.23
27	AERQ_1Z24FH24	38	\$76.80	\$2,918.22
28	AERQ_1ZA20FJB20	62	\$46.87	\$2,906.18
29	AERQ_1BA20MP20	110	\$25.91	\$2,849.63
30	AERQ_1BA16FJC16	53	\$53.46	\$2,833.18
31	AERQ_1B20FHA20	41	\$68.54	\$2,810.20
32	AERQ_1BA12FRA12	78	\$35.81	\$2,793.04
33	AERQ_1B16FLA20	7	\$382.13	\$2,674.90
34	AERQ_1EA20FR20	33	\$75.90	\$2,504.82
35	AERQ_1B16FHA16	58	\$42.49	\$2,464.15
36	AERQ_1B16FLA16	84	\$28.95	\$2,431.42
37	AERQ_1B16FL16	97	\$24.78	\$2,403.44
38	AERQ_1BA16MP16	137	\$17.32	\$2,373.07
39	AERQ_1ZA20FRB20	44	\$53.82	\$2,368.12
40	AERQ_1B12FLA12	91	\$24.39	\$2,219.51
41	AERQ_1BA20FR16	42	\$52.43	\$2,201.91
42	AERQ_1B16FLA12	77	\$28.14	\$2,167.01
43	AERQ_1B20FL16	56	\$37.90	\$2,122.21
44	AERQ_1B16FL12	98	\$21.63	\$2,119.40
45	AERQ_1Z24FHB24	16	\$128.87	\$2,061.95
46	AERQ_1ZA20FRA20	30	\$68.43	\$2,052.87

LOT 4030 AEROQUIP JAN. 2023 - DEADSTOCK BROKER

	A	B	E	F
1	PART #	QTY	UNIT REPLACEMENT COST USD	TOTAL REPLACEMENT COST USD
47	AERQ_1B24FLB20	37	\$55.12	\$2,039.26
48	AERQ_1B20FLB16	42	\$48.13	\$2,021.42
49	AERQ_1BA16FJ20	50	\$40.19	\$2,009.32
50	AERQ_1B12FH12	83	\$24.00	\$1,992.41
51	AERQ_1B16FL20	35	\$56.09	\$1,963.14
52	AERQ_1B12FLB12	86	\$22.03	\$1,894.61
53	AERQ_1Z20FLB20	21	\$88.30	\$1,854.22
54	AERQ_1BA16FRC16	46	\$40.28	\$1,853.04
55	AERQ_1B32FLB32	19	\$96.90	\$1,841.16
56	AERQ_1BA12FJ16	67	\$27.05	\$1,812.45
57	AERQ_1B20FH16	45	\$40.27	\$1,812.18
58	AERQ_1E16FL16	53	\$33.59	\$1,780.22
59	AERQ_1B16FLB16	63	\$27.77	\$1,749.35
60	AERQ_1BA16FR12	53	\$32.84	\$1,740.49
61	AERQ_1BA16MJ16	69	\$25.10	\$1,731.76
62	AERQ_1EA16FRA16	28	\$61.53	\$1,722.88
63	AERQ_1BA10FJ12	113	\$15.14	\$1,710.66
64	AERQ_1B32FLB24	13	\$130.74	\$1,699.63
65	AERQ_1E20FHA16	18	\$93.91	\$1,690.32
66	AERQ_1EA20FR16	27	\$62.44	\$1,685.94
67	AERQ_1EA24MP24	23	\$71.52	\$1,644.88
68	AERQ_1BA12FJC12	50	\$32.89	\$1,644.58
69	AERQ_1BA20MP16	40	\$40.94	\$1,637.50
70	AERQ_1Z20FHB20	30	\$54.23	\$1,626.94
71	AERQ_1B16FHB12	40	\$39.67	\$1,586.63
72	AERQ_1B20FHA16	35	\$45.26	\$1,584.23
73	AERQ_1BA12FRB12	46	\$34.23	\$1,574.57
74	AERQ_1B32FLA32	16	\$97.87	\$1,565.97
75	AERQ_1EA20FRB16	30	\$51.74	\$1,552.25
76	AERQ_1E16FLB16	47	\$32.69	\$1,536.48
77	AERQ_1EA12FJ12	88	\$17.16	\$1,510.40
78	AERQ_1B20FHB20	25	\$59.62	\$1,490.62
79	AERQ_1E20CT16	24	\$62.02	\$1,488.55
80	AERQ_1BA24FJ20	24	\$61.35	\$1,472.29
81	AERQ_1B12FL12	87	\$16.88	\$1,468.88
82	AERQ_1BA20MR20	61	\$23.91	\$1,458.42
83	AERQ_1E16CT16	29	\$50.22	\$1,456.33
84	AERQ_1B24FL24	8	\$180.63	\$1,445.02
85	AERQ_1E12FHA12	36	\$39.23	\$1,412.34
86	AERQ_1E16CTB16	25	\$56.27	\$1,406.63
87	AERQ_1B16FH12	47	\$29.63	\$1,392.77
88	AERQ_1BA32FJ32	16	\$82.91	\$1,326.57
89	AERQ_1Z24FHA20	18	\$73.39	\$1,321.08
90	AERQ_1BA12FJ12	99	\$13.32	\$1,318.79
91	AERQ_1B20KF20	15	\$87.06	\$1,305.85

LOT 4030 AEROQUIP JAN. 2023 - DEADSTOCK BROKER

	A	B	E	F
1	PART #	QTY	UNIT REPLACEMENT COST USD	TOTAL REPLACEMENT COST USD
92	AERQ_1Z20FH20	26	\$50.12	\$1,303.11
93	AERQ_1BA16MJ12	60	\$21.68	\$1,300.79
94	AERQ_1B24FL20	30	\$43.29	\$1,298.63
95	AERQ_1ZA32MP32	9	\$144.23	\$1,298.07
96	AERQ_1BA10FJ10	100	\$12.88	\$1,287.65
97	AERQ_1ZA20FR20	18	\$69.47	\$1,250.38
98	AERQ_1B16FLB20	20	\$62.18	\$1,243.54
99	AERQ_1B24FH24	21	\$57.96	\$1,217.13
100	AERQ_1E20FH16	21	\$57.68	\$1,211.38
101	AERQ_1B12FHA12	41	\$29.30	\$1,201.37
102	AERQ_1Z20FL20	20	\$59.45	\$1,188.97
103	AERQ_1E20FL20	21	\$56.04	\$1,176.75
104	AERQ_1E20CTB16	16	\$72.96	\$1,167.30
105	AERQ_1Z20FHA20	20	\$57.43	\$1,148.63
106	AERQ_1EA12FRB12	24	\$47.62	\$1,142.98
107	AERQ_1BA20MJ20	34	\$33.59	\$1,142.11
108	AERQ_1BA12MJ12	81	\$14.01	\$1,134.98
109	AERQ_1E20CTF16	15	\$74.78	\$1,121.75
110	AERQ_1EA12FRA12	32	\$35.00	\$1,119.95
111	AERQ_1EA16MP16	37	\$30.20	\$1,117.55
112	AERQ_1ZA20FJA20	24	\$46.53	\$1,116.63
113	AERQ_1EA16FJ16	45	\$24.36	\$1,096.00
114	AERQ_1B20FL12	43	\$25.09	\$1,078.85
115	AERQ_1B16KF16	22	\$48.47	\$1,066.36
116	AERQ_1BA20FJ20	28	\$37.16	\$1,040.58
117	AERQ_1BA16FRB12	25	\$41.29	\$1,032.32
118	AERQ_1B24FH20	12	\$81.48	\$977.75
119	AERQ_1B16BF16	39	\$25.06	\$977.48
120	AERQ_1B16FH16	31	\$31.22	\$967.86
121	AERQ_1E12FH12	43	\$22.13	\$951.67
122	AERQ_1B24FLA24	14	\$67.91	\$950.75
123	AERQ_1EA16FJB16	17	\$55.54	\$944.11
124	AERQ_1BA24MJ24	9	\$104.43	\$939.87
125	AERQ_1B24FHA24	10	\$93.51	\$935.07
126	AERQ_1BA12FRC12	30	\$31.12	\$933.62
127	AERQ_1B20FHB16	17	\$54.18	\$921.00
128	AERQ_1ZA16FRA16	16	\$56.91	\$910.61
129	AERQ_1EA16FRA12	12	\$74.77	\$897.23
130	AERQ_1E25DS16	17	\$52.45	\$891.66
131	AERQ_1B16FHB16	22	\$40.46	\$890.20
132	AERQ_1BA24MP24	22	\$39.26	\$863.72
133	AERQ_1E20FLB20	14	\$60.69	\$849.63
134	AERQ_1E16FHA16	19	\$44.43	\$844.25
135	AERQ_1B24FLA20	15	\$55.96	\$839.42
136	AERQ_1EA16FRB12	14	\$59.75	\$836.51

LOT 4030 AEROQUIP JAN. 2023 - DEADSTOCK BROKER

	A	B	E	F
1	PART #	QTY	UNIT REPLACEMENT COST USD	TOTAL REPLACEMENT COST USD
137	AERQ_1E20FLA16	12	\$69.23	\$830.71
138	AERQ_1BA10FJB10	37	\$22.42	\$829.37
139	AERQ_1BA16MP12	51	\$15.98	\$815.05
140	AERQ_1BA16FJ12	40	\$20.18	\$807.26
141	AERQ_1E20CTB20	10	\$80.26	\$802.59
142	AERQ_1BA16MR12	33	\$23.99	\$791.53
143	AERQ_1Z24FHB20	8	\$98.85	\$790.82
144	AERQ_1E20FH20	13	\$60.81	\$790.58
145	AERQ_1Z20CTB20	12	\$65.54	\$786.47
146	AERQ_1B12FHB12	22	\$34.77	\$765.00
147	AERQ_1BA8MP12	29	\$25.88	\$750.61
148	AERQ_1E20CTA20	12	\$62.31	\$747.78
149	AERQ_1E12FHB12	21	\$35.58	\$747.13
150	AERQ_1E12FL12	27	\$27.55	\$743.74
151	AERQ_1EA20FJB20	9	\$81.98	\$737.79
152	AERQ_1B24FL16	18	\$40.86	\$735.41
153	AERQ_1EA20FRA20	9	\$81.52	\$733.68
154	AERQ_1Z32FH32	4	\$182.45	\$729.81
155	AERQ_1E24FL24	20	\$36.48	\$729.54
156	AERQ_1B32FL32	9	\$80.18	\$721.63
157	AERQ_1B12FLG12	33	\$21.77	\$718.56
158	AERQ_1ZA24FR24	9	\$79.82	\$718.40
159	AERQ_1B32FLA24	10	\$71.54	\$715.36
160	AERQ_1B12BF12	44	\$16.19	\$712.45
161	AERQ_1B16BFA16	15	\$47.43	\$711.51
162	AERQ_1E12FLA12	22	\$32.22	\$708.83
163	AERQ_1E20CT20	15	\$47.23	\$708.43
164	AERQ_1EA20FRB20	11	\$64.18	\$705.93
165	AERQ_1ZA24FJB24	11	\$63.43	\$697.76
166	AERQ_1B20FLB12	16	\$43.52	\$696.31
167	AERQ_1BA10FR12	26	\$26.62	\$692.12
168	AERQ_1E16FH12	20	\$34.54	\$690.87
169	AERQ_1B24FHB20	10	\$67.76	\$677.62
170	AERQ_1BA24FR24	8	\$84.63	\$677.02
171	AERQ_1B16BFB16	20	\$33.63	\$672.65
172	AERQ_1B16FLD16	17	\$38.03	\$646.48
173	AERQ_1Z24CTA24	15	\$42.81	\$642.21
174	AERQ_1E16FHB12	24	\$26.64	\$639.35
175	AERQ_1E16FLA16	17	\$37.25	\$633.33
176	AERQ_1EA12FR12	23	\$27.43	\$630.78
177	AERQ_1Z20CTB16	9	\$69.86	\$628.75
178	AERQ_1EA12FJB12	22	\$27.77	\$610.96
179	AERQ_1ZA16FR16	12	\$50.69	\$608.25
180	AERQ_1E20FLA20	10	\$60.41	\$604.10
181	AERQ_1Z24CTG24	9	\$65.56	\$590.00

LOT 4030 AEROQUIP JAN. 2023 - DEADSTOCK BROKER

	A	B	E	F
1	PART #	QTY	UNIT REPLACEMENT COST USD	TOTAL REPLACEMENT COST USD
182	AERQ_1Z16FHB16	12	\$48.05	\$576.61
183	AERQ_1Z32FL24	5	\$114.44	\$572.22
184	AERQ_1BA6FRB6	49	\$11.56	\$566.33
185	AERQ_1Z32CTB32	5	\$111.77	\$558.83
186	AERQ_1Z32FHA32	3	\$186.11	\$558.32
187	AERQ_1Z24FH20	9	\$61.99	\$557.90
188	AERQ_1E16FH16	13	\$42.45	\$551.88
189	AERQ_1BA20FRC20	6	\$90.34	\$542.04
190	AERQ_1EA20FJ16	12	\$45.09	\$541.04
191	AERQ_1E32FLA32	4	\$134.68	\$538.70
192	AERQ_1B12KF12	32	\$16.81	\$537.81
193	AERQ_1Z24FL24	6	\$89.35	\$536.12
194	AERQ_1B8FHB8	12	\$44.60	\$535.15
195	AERQ_1B20BFB20	7	\$75.33	\$527.34
196	AERQ_1B16FLG16	17	\$30.93	\$525.89
197	AERQ_1Z20FLA20	7	\$74.45	\$521.18
198	AERQ_1ZA24MP24	6	\$85.66	\$513.94
199	AERQ_1EA24FJB24	6	\$85.62	\$513.69
200	AERQ_1EA20FJ20	11	\$45.92	\$505.14
201	AERQ_1B20FLD16	9	\$55.31	\$497.81
202	AERQ_1BA14MJ12	14	\$34.97	\$489.54
203	AERQ_1B25DSA16	5	\$97.39	\$486.95
204	AERQ_1E32FL32	4	\$117.13	\$468.52
205	AERQ_1B20BF20	10	\$46.84	\$468.43
206	AERQ_1E12FLB12	15	\$30.47	\$457.01
207	AERQ_1B12BFB12	18	\$25.27	\$454.90
208	AERQ_1E12CTB12	10	\$45.48	\$454.81
209	AERQ_1B12FLA8	13	\$34.88	\$453.40
210	AERQ_1E16FL12	12	\$36.73	\$440.77
211	AERQ_1B20DL12	17	\$25.74	\$437.61
212	AERQ_1B20DSB12	12	\$36.35	\$436.19
213	AERQ_1E20FHB16	5	\$85.85	\$429.26
214	AERQ_1Z32DSB20	5	\$85.42	\$427.09
215	AERQ_1B12FLF12	19	\$22.39	\$425.38
216	AERQ_1BA16MR16	17	\$24.96	\$424.27
217	AERQ_1B32FH32	4	\$104.87	\$419.48
218	AERQ_1Z32CTB24	2	\$206.82	\$413.63
219	AERQ_1Z24CTB24	4	\$103.35	\$413.38
220	AERQ_1Z20CTA20	9	\$44.89	\$403.97
221	AERQ_1B16FLE16	11	\$36.39	\$400.34
222	AERQ_1B12BFA12	16	\$24.98	\$399.61
223	AERQ_1E25DSA16	6	\$63.75	\$382.53
224	AERQ_1Z20CT16	8	\$47.81	\$382.50
225	AERQ_1EA16FJA16	8	\$47.72	\$381.74
226	AERQ_1B12FLE12	14	\$27.14	\$380.03

LOT 4030 AEROQUIP JAN. 2023 - DEADSTOCK BROKER

	A	B	E	F
1	PART #	QTY	UNIT REPLACEMENT COST USD	TOTAL REPLACEMENT COST USD
227	AERQ_1BA14FJ12	15	\$24.92	\$373.87
228	AERQ_1Z16FH16	9	\$41.07	\$369.59
229	AERQ_1B25DL16	10	\$36.93	\$369.31
230	AERQ_1Z32CTA32	2	\$178.58	\$357.15
231	AERQ_1B16FLG12	9	\$39.33	\$353.97
232	AERQ_1B16FLF12	8	\$43.07	\$344.57
233	AERQ_1EA12FJA12	8	\$42.68	\$341.45
234	AERQ_1B16FLF16	8	\$42.24	\$337.88
235	AERQ_1Z32CT32	2	\$163.73	\$327.46
236	AERQ_1Z20CT20	7	\$46.42	\$324.94
237	AERQ_1B8FH8	11	\$29.44	\$323.87
238	AERQ_1B20FLE16	6	\$53.11	\$318.64
239	AERQ_1E32FLB32	2	\$156.35	\$312.70
240	AERQ_1B25DSB16	4	\$77.89	\$311.55
241	AERQ_1B16JF16	6	\$51.63	\$309.78
242	AERQ_1B20DS12	14	\$21.72	\$304.11
243	AERQ_1E20FLB16	4	\$75.09	\$300.35
244	AERQ_1Z32FLA32	2	\$145.40	\$290.80
245	AERQ_1Z20CTG20	4	\$72.56	\$290.23
246	AERQ_1Z32FLB32	2	\$144.58	\$289.15
247	AERQ_1B20DSA12	6	\$47.10	\$282.58
248	AERQ_1BA12FR8	10	\$27.96	\$279.61
249	AERQ_1Z16CTA16	7	\$39.55	\$276.85
250	AERQ_1E16FLB12	5	\$55.04	\$275.22
251	AERQ_1BA12MR12	12	\$22.71	\$272.50
252	AERQ_1E16CTB12	6	\$45.38	\$272.31
253	AERQ_1B8FLA8	15	\$17.82	\$267.29
254	AERQ_1Z32CT24	2	\$126.96	\$253.92
255	AERQ_1E24FHB20	2	\$126.03	\$252.07
256	AERQ_1B20FLG16	5	\$49.81	\$249.04
257	AERQ_1E12CTG12	6	\$40.79	\$244.75
258	AERQ_1EA12MP12	8	\$30.49	\$243.90
259	AERQ_1Z32FHB32	1	\$241.76	\$241.76
260	AERQ_1Z24CTB20	2	\$120.38	\$240.75
261	AERQ_1B32FLD32	2	\$119.58	\$239.16
262	AERQ_1ZA24FJA24	3	\$78.85	\$236.54
263	AERQ_1Z32CTA24	1	\$233.49	\$233.49
264	AERQ_1BA12MP16	12	\$19.41	\$232.90
265	AERQ_1EA24FJA24	3	\$75.57	\$226.71
266	AERQ_1B12JF12	7	\$32.33	\$226.33
267	AERQ_1BA32MP32	4	\$56.52	\$226.10
268	AERQ_1E16FHA12	4	\$55.94	\$223.77
269	AERQ_1E16BF16	6	\$36.60	\$219.60
270	AERQ_1EA16FJA12	5	\$43.28	\$216.39
271	AERQ_1B24FHG24	1	\$215.83	\$215.83

LOT 4030 AEROQUIP JAN. 2023 - DEADSTOCK BROKER

	A	B	E	F
1	PART #	QTY	UNIT REPLACEMENT COST USD	TOTAL REPLACEMENT COST USD
272	AERQ_1Z24FLA24	2	\$105.10	\$210.19
273	AERQ_1Z24CTA20	2	\$102.57	\$205.13
274	AERQ_1E24FLA20	2	\$101.47	\$202.93
275	AERQ_1B24FLB16	13	\$15.24	\$198.12
276	AERQ_1BA12FR16	7	\$27.44	\$192.08
277	AERQ_1Z24CT20	2	\$95.59	\$191.17
278	AERQ_1BA12FRB8	5	\$38.03	\$190.14
279	AERQ_1EA20FJA20	4	\$45.56	\$182.26
280	AERQ_1E12CTA12	5	\$35.98	\$179.91
281	AERQ_1B32DL20	4	\$43.22	\$172.88
282	AERQ_1B8FLB8	10	\$17.09	\$170.87
283	AERQ_1E20FHA20	2	\$85.06	\$170.13
284	AERQ_1Z16CT16	3	\$56.68	\$170.05
285	AERQ_1B24FLF20	2	\$84.13	\$168.27
286	AERQ_1EA32MP32	1	\$160.97	\$160.97
287	AERQ_1B25DS16	4	\$39.43	\$157.71
288	AERQ_1BA6FJC6	3	\$51.88	\$155.63
289	AERQ_1E20CTA16	2	\$76.24	\$152.48
290	AERQ_1BA24FJ24	3	\$50.18	\$150.54
291	AERQ_1Z16FLB16	2	\$74.05	\$148.11
292	AERQ_1Z32FL32	2	\$73.32	\$146.63
293	AERQ_1E16FHB16	3	\$48.68	\$146.05
294	AERQ_1BA10MJ12	5	\$29.10	\$145.50
295	AERQ_1ZA16FJB16	2	\$69.65	\$139.31
296	AERQ_1E20CTG16	2	\$69.56	\$139.12
297	AERQ_1E20CTD16	2	\$69.35	\$138.69
298	AERQ_1Z24CTE20	1	\$136.58	\$136.58
299	AERQ_1B24FLB24	2	\$68.10	\$136.20
300	AERQ_1ZA16FJ16	4	\$33.98	\$135.90
301	AERQ_1E12CTE12	4	\$33.60	\$134.38
302	AERQ_1Z20CTA16	2	\$65.98	\$131.96
303	AERQ_1B20FLE20	2	\$64.71	\$129.41
304	AERQ_1B25EK16	2	\$61.80	\$123.60
305	AERQ_1EA20FJB16	2	\$59.93	\$119.86
306	AERQ_1BA16FJ16	6	\$19.03	\$114.19
307	AERQ_1E16CTA12	2	\$55.37	\$110.73
308	AERQ_1Z24FLB24	1	\$109.83	\$109.83
309	AERQ_1B20EK12	4	\$27.13	\$108.53
310	AERQ_1Z32FH24	1	\$106.79	\$106.79
311	AERQ_1EA16FJ12	4	\$26.68	\$106.73
312	AERQ_1B24FHA20	1	\$97.09	\$97.09
313	AERQ_1E16CT12	2	\$48.44	\$96.88
314	AERQ_1ZA16FRB16	2	\$48.13	\$96.25
315	AERQ_1B24FLF24	5	\$18.87	\$94.33
316	AERQ_1B24FLD24	1	\$88.79	\$88.79

	A	B	E	F
1	PART #	QTY	UNIT REPLACEMENT COST USD	TOTAL REPLACEMENT COST USD
317	AERQ_1BA12FJ8	7	\$12.37	\$86.56
318	AERQ_1EA24FJ24	2	\$42.43	\$84.87
319	AERQ_1B20BFA20	1	\$81.09	\$81.09
320	AERQ_1B20FLA12	2	\$38.55	\$77.10
321	AERQ_1B32FLE32	4	\$18.95	\$75.82
322	AERQ_1E24FHA24	1	\$74.79	\$74.79
323	AERQ_1BA10MJ8	7	\$10.37	\$72.56
324	AERQ_1E20FHB20	1	\$72.21	\$72.21
325	AERQ_1BA24FR20	1	\$68.31	\$68.31
326	AERQ_1ZA20FRA16	1	\$66.51	\$66.51
327	AERQ_1BA10FR10	4	\$15.38	\$61.54
328	AERQ_1Z20FH16	1	\$54.17	\$54.17
329	AERQ_1Z16CTB16	1	\$50.74	\$50.74
330	AERQ_1B20FH20	1	\$46.02	\$46.02
331	AERQ_1B12FLD12	6	\$7.60	\$45.58
332	AERQ_1BA10FRB10	2	\$21.38	\$42.77
333	AERQ_1EA16FR16	1	\$42.49	\$42.49
334	AERQ_1B32FL24	2	\$20.55	\$41.11
335	AERQ_1BA8FJA6	1	\$40.08	\$40.08
336	AERQ_1BA12MJ8	3	\$12.82	\$38.45
337	AERQ_1B8FL8	3	\$12.69	\$38.07
338	AERQ_1B20DL10	2	\$15.87	\$31.73
339	AERQ_1BA8FJA8	2	\$15.45	\$30.89
340	AERQ_1B16EK10	1	\$29.15	\$29.15
341	AERQ_1BA16MB16	2	\$13.60	\$27.20
342	AERQ_1BA16FRA12	1	\$26.37	\$26.37
343	AERQ_1BA6FJ6	3	\$8.75	\$26.24
344	AERQ_1BA10FJB8	1	\$24.61	\$24.61
345	AERQ_1BA8MJ8	2	\$9.72	\$19.43
346	AERQ_1BA10MJ10	1	\$12.82	\$12.82
347	AERQ_1E12CT12	5	\$0.01	\$0.05
348	AERQ_1ZA24FRB24	3	\$0.01	\$0.03
349	AERQ_1BA24FRB24	8	\$0.00	\$0.00
350				\$448,926.04
351				
352				
353	REPLACEMENT COSTS ARE SHOWN FOR <i>REFERENCE ONLY</i>			
354	MINIMUM ORDERS APPLY			
355	THIS LOT CAN BE PURCHASED IN WHOLE OR PART			
356	SUPPLIER IS LOOKING FOR REASONABLE OFFERS ON ALL OR PART OF THIS INVENTORY			
357	MILLIONS MORE AT 35% - 60% DISCOUNT ON OUR WEBSITE			
358	DOES YOUR VENDOR GIVE YOU EXTRA DISCOUNTS?? - WE DO!!			
359	ALL PRODUCT GUARANTEED!!			

	A	B	E	F
1	PART #	QTY	UNIT REPLACEMENT COST USD	TOTAL REPLACEMENT COST USD
360	MAKE OFFERS!!			
361	WWW.DEADSTOCKBROKER.COM E-MAIL: inventory@deadstockbroker.com			