

LOT 1044 PARKER GEAR PUMPS FEB. 2010

	A	B	C	D	E
1	PART #	DESCRIPTION	QTY	UNIT REPLACEMENT COST	TOTAL REPLACEMENT COST
2	0013552	WASHER PVP16	4	\$0.72	\$2.88
3	0015433	KIT, ADPTK CP16 MTG CH*	10	\$12.88	\$128.80
4	0015433	KIT, ADPTK CP16 MTG CH*	3	\$12.88	\$38.64
5	0015433	KIT, ADPTK CP16 MTG CH*	3	\$12.88	\$38.64
6	0015483	KIT, SEAL M20 SERIES	2	\$14.11	\$28.22
7	0015711	NIPPLE	5	\$10.13	\$50.65
8	0027204	GEAR, DG P16 100 #5 D,N,F,S&T	5	\$56.46	\$282.30
9	0027204	GEAR, DG P16 100 #5 D,N,F,S&T	1	\$56.46	\$56.46
10	0027222	GEAR, DG P16 45 #2 E,G,J&H	6	\$89.69	\$538.14
11	0027224	GEAR, DG P16 85 #2 E,G,J&H	1	\$42.12	\$42.12
12	0027231	GEAR, DG P16 65 #5 E,G,J&H	1	\$61.13	\$61.13
13	0027236	GEAR, DG P16 180 #5 E,G,J&H	7	\$114.95	\$804.65
14	0027237	GEAR, DG P16 200 #5 E,G,J&H	3	\$52.32	\$156.96
15	0027276	GEAR, DG TP16 65 #5 D,N,F,S&T	1	\$74.74	\$74.74
16	0027277	GEAR, DG TP16 85 #5 D,N,F,S&T	2	\$100.17	\$200.34
17	0027285	GEAR, DG TP16 85 #2 E,G,J&H	2	\$68.07	\$136.14
18	0027298	TP16-DG (200) "5+"	2	\$56.98	\$113.96
19	0027302	GEAR, RDG TP16 100 1.25 BL	2	\$50.00	\$100.00
20	0027306	GEAR, RDG TP16 200 1.25 BL	1	\$56.89	\$56.89
21	0027399	GEAR, DG P16 85 #6 D,N,F,S&T	3	\$61.48	\$184.44
22	0027399	GEAR, DG P16 85 #6 D,N,F,S&T	2	\$61.48	\$122.96
23	0027400	GEAR, DG P16 100 #6 D,N,F,S&T	2	\$57.86	\$115.72
24	0027400	GEAR, DG P16 100 #6 D,N,F,S&T	1	\$57.86	\$57.86
25	0027415	GEAR, DG CP16 150	5	\$58.16	\$290.80
26	0027415	GEAR, DG CP16 150	3	\$58.16	\$174.48
27	0027430	GEAR, DG P16 65 #1 D,N,F,S&T	2	\$80.28	\$160.56
28	0027430	GEAR, DG P16 65 #1 D,N,F,S&T	2	\$80.28	\$160.56
29	0027430	GEAR, DG P16 65 #1 D,N,F,S&T	2	\$80.28	\$160.56
30	0027504	GEAR, DG CP16 65	5	\$61.29	\$306.45
31	0027505	GEAR, DG CP16 85	6	\$61.44	\$368.64
32	0027505	GEAR, DG CP16 85	1	\$61.44	\$61.44
33	0027506	GEAR, DG CP16 100	4	\$44.59	\$178.36
34	0027506	GEAR, DG CP16 100	3	\$44.59	\$133.77
35	0027507	GEAR, DG CP16 115	3	\$46.21	\$138.63
36	0027507	GEAR, DG CP16 115	2	\$46.21	\$92.42
37	0027508	GEAR, DG CP16 180	4	\$52.32	\$209.28
38	0027508	GEAR, DG CP16 180	3	\$52.32	\$156.96
39	0027509	GEAR, DG CP16 200	2	\$75.96	\$151.92
40	0027509	GEAR, DG CP16 200	2	\$75.96	\$151.92
41	0027757	CPLG, .68 9T .88 13T 1.328 LG	1	\$46.70	\$46.70
42	0027779	GEAR, DG P16 180 #9 D FLG	4	\$67.46	\$269.84
43	0027948	GEAR, DG P16 100 #1 D,N,F,S&T	1	\$74.49	\$74.49
44	0033299	ADAPTER P/B 2BOLTA	8	\$20.92	\$167.36
45	0033429	GEAR PLATE, P16 45	10	\$28.69	\$286.90
46	0033429	GEAR PLATE, P16 45	2	\$28.69	\$57.38
47	0033429	GEAR PLATE, P16 45	1	\$28.69	\$28.69
48	0033755	GEAR BODY	2	\$41.62	\$83.24
49	0061211	COVER PLATE, PVP16 #6 ST THD R	2	\$135.76	\$271.52

	A	B	C	D	E
1	PART #	DESCRIPTION	QTY	UNIT REPLACEMENT COST	TOTAL REPLACEMENT COST
50	0086580	62B 5 10HG8 SHCS NC	6	\$0.18	\$1.08
51	0086765	62B 8 32HG8 SHCS NC	99	\$1.02	\$100.98
52	0086767	62B 8 36HG8 SHCS NC	32	\$1.39	\$44.48
53	0086774	62B 8 42HG8 SHCS NC	25	\$1.75	\$43.75
54	0086774	62B 8 42HG8 SHCS NC	24	\$1.75	\$42.00
55	0120623	P16-115A-2N1 CH*	8	\$294.11	\$2,352.88
56	0120771	P16 150C 2N3	1	\$303.70	\$303.70
57	0120790	P16 150C 2N9	1	\$303.72	\$303.72
58	0120910	P16 180A 2S2	2	\$337.79	\$675.58
59	716067	DRIVE GEAR ASSY D27	1	\$35.11	\$35.11
60	0900249	MGG20010 BA2A3	5	\$146.90	\$734.50
61	0909101	MOUNTING PLATE ORDE	6	\$11.51	\$69.06
62	0909102	REPLACES 7323-001	1	\$11.51	\$11.51
63	3011135006	F1135-2 SHAFT	1	\$41.79	\$41.79
64	3012805000	GEAR SET	2	\$102.44	\$204.88
65	3012825000	E1006M-25 GEAR	2	\$120.50	\$241.00
66	3021134005	BN1134	2	\$37.80	\$75.60
67	3021134005	BN1134	1	\$37.80	\$37.80
68	3021134018	JB1134 SHAFT	10	\$35.20	\$352.00
69	3025035204	PARKER PART	2	\$39.18	\$78.36
70	3031135006	SFT,CONT=(25X)06Tx0.87D,21Tx.90D,5	6	\$33.83	\$202.98
71	3031135006	SFT,CONT=(25X)06Tx0.87D,21Tx.90D,5	1	\$33.83	\$33.83
72	3031135006	SFT,CONT=(25X)06Tx0.87D,21Tx.90D,5	1	\$33.83	\$33.83
73	3051134005	CF1134 SHAFT	3	\$48.96	\$146.88
74	3051134005	CF1134 SHAFT	1	\$48.96	\$48.96
75	3051134005	CF1134 SHAFT	1	\$48.96	\$48.96
76	3051134013	CP1134 SHAFT	1	\$22.70	\$22.70
77	3055031206	DE1686-3 37X	2	\$58.35	\$116.70
78	3085016201	SECOV=(G101)PAD-MTG,MACH,.50-13THD	1	\$41.47	\$41.47
79	3085043201	SECOV=(P20)6-BLT-RD,2.62PLT,MACH	5	\$34.30	\$171.50
80	3085043201	SECOV=(P20)6-BLT-RD,2.62PLT,MACH	2	\$34.30	\$68.60
81	3085043401	SECOV=(P20)6-BLT-RD,2.62PLT,.25NPT	3	\$45.09	\$135.27
82	3122910202	SET,SFT+GEAR=(030)6Tx1.00D-SPLN,1.00	1	\$82.15	\$82.15
83	3122915830	SET,SFT+GEAR=(030)KWY,.25x1.00-0.88D,	1	\$94.16	\$94.16
84	3122917130	SET,SFT+GEAR=(030)13Tx0.86D-SPLN,1.	3	\$77.01	\$231.03
85	3122917130	SET,SFT+GEAR=(030)13Tx0.86D-SPLN,1.	2	\$77.01	\$154.02
86	3122917640	SET,SFT+GEAR=(030)KWY,.25x1.25-1.00D,	1	\$83.89	\$83.89
87	3122917640	SET,SFT+GEAR=(030)KWY,.25x1.25-1.00D,	1	\$83.89	\$83.89
88	3122917840	CODE 67	5	\$83.55	\$417.75
89	3122917840	CODE 67	1	\$83.55	\$83.55
90	3123220903	PECOV=(031)SCALLOP,PRIV-MACH,.88X.88	1	\$48.50	\$48.50
91	3128212226	GEAR HOUSING	5	\$49.20	\$246.00
92	3131133011	SFT,CONN=(050)21Tx0.90D,21Tx0.90D,	7	\$16.51	\$115.57
93	3131133011	SFT,CONN=(050)21Tx0.90D,21Tx0.90D,	1	\$16.51	\$16.51
94	3132812008	SET,DR+DRN=(WM51)13TX2.4D,1.25GW,21T	1	\$53.60	\$53.60
95	3132912330	SET,SFT+GEAR=(050)13TX0.85D-SPLN,12G	8	\$94.79	\$758.32
96	3132912640	GEAR SHFT	5	\$82.86	\$414.30
97	3132917650	SET,SFT+GEAR=(050)KWY.31X1.50-1.25D,	5	\$88.62	\$443.10

	A	B	C	D	E
1	PART #	DESCRIPTION	QTY	UNIT REPLACEMENT COST	TOTAL REPLACEMENT COST
98	3132920350	SET,SFT+GEAR=(050)14TX1.22D-SPLN,2.0	3	\$109.26	\$327.78
99	3135023401	SEC2C 1/4NPT50	4	\$46.40	\$185.60
100	3135027205	SECOV=(051)2-BLT-WG,4.00PLT	4	\$48.14	\$192.56
101	3135027205	SECOV=(051)2-BLT-WG,4.00PLT	1	\$48.14	\$48.14
102	3135027205	SECOV=(051)2-BLT-WG,4.00PLT	1	\$48.14	\$48.14
103	3135027205	SECOV=(051)2-BLT-WG,4.00PLT	1	\$48.14	\$48.14
104	3135027205	SECOV=(051)2-BLT-WG,4.00PLT	1	\$48.14	\$48.14
105	3135047201	SECOV=(051)6-BLT-RD,2.62PLT,DOWEL-	13	\$49.17	\$639.21
106	3144000101	CAP,VALVE=(C101)4.7L,.12NPT	15	\$44.44	\$666.60
107	3144000101	CAP,VALVE=(C101)4.7L,.12NPT	1	\$44.44	\$44.44
108	3145039201	SECOV=(C101)4-BLTx3.56CTR,MACH	3	\$29.81	\$89.43
109	3162910150	GEAR/SHFT 7A75	14	\$90.68	\$1,269.52
110	3162912150	GEAR/SHFT 7A75	12	\$91.51	\$1,098.12
111	3165033408	SECOV=(075)4-BLT-SQ,4.00PLT,.25NPT-D	8	\$85.10	\$680.80
112	3167370100	BRG-CARR=(075)7.2W,.25ODT-RLF	2	\$81.10	\$162.20
113	3172815000	PARKER PART	25	\$274.69	\$6,867.25
114	3172815000	PARKER PART	3	\$274.69	\$824.07
115	3172817000	PARKER PART	8	\$305.01	\$2,440.08
116	3172817000	PARKER PART	8	\$305.01	\$2,440.08
117	3172820000	PARKER PART	14	\$314.56	\$4,403.84
118	3172820000	PARKER PART	10	\$314.56	\$3,145.60
119	3177323100	PARKER PART	1	\$389.26	\$389.26
120	3177323100	PARKER PART	1	\$389.26	\$389.26
121	3222907250	SET,SFT+GEAR=(365)9TX1.22D-SPLN,0.7	3	\$109.04	\$327.12
122	3222907750	GEAR/SHFT	6	\$103.93	\$623.58
123	3222910750	SET,SFT+GEAR=(365)KWY.31X1.50-1.25D	4	\$110.25	\$441.00
124	3222920650	SET,SFT+G=(365)KWY.31X1.50-1.25D,2.0	16	\$115.54	\$1,848.64
125	3222920650	SET,SFT+G=(365)KWY.31X1.50-1.25D,2.0	3	\$115.54	\$346.62
126	3222920650	SET,SFT+G=(365)KWY.31X1.50-1.25D,2.0	2	\$115.54	\$231.08
127	3222920650	SET,SFT+G=(365)KWY.31X1.50-1.25D,2.0	1	\$115.54	\$115.54
128	3223064100	PECOV/PB=(365)CCW,2-BLT,4.00PLT,..25O	4	\$93.11	\$372.44
129	3223112285	PECOV/BSHG=(365)2.0x1.5SF	2	\$77.57	\$155.14
130	3223112285	PECOV/BSHG=(365)2.0x1.5SF	1	\$77.57	\$77.57
131	3223150285	PEC 2"X1.5"FL	4	\$140.58	\$562.32
132	3223162902	PUMP	1	\$125.49	\$125.49
133	3229111013	P365A142FJAB20-11	1	\$684.47	\$684.47
134	3229122007	PGP365B298N0AB22-7J	7	\$658.52	\$4,609.64
135	3229130080	PGP365B178EK*AB22-7HCAB15-1HCAB*12-1	6	\$2,046.84	\$12,281.04
136	3229210061	PGM365A878*VCEB20-11	12	\$819.37	\$9,832.44
137	3229210061	PGM365A878*VCEB20-11	7	\$819.37	\$5,735.59
138	3232910150	SET,SFT+GEAR=(350)14Tx1.22D-SPLN,1	1	\$90.84	\$90.84
139	3232910650	SET,SFT+GEAR=(350)KWY.31X1.5-1.25D,1	4	\$112.12	\$448.48
140	3232910752	P350 GEAR SFT	1	\$93.70	\$93.70
141	3232912650	SET,SFT+GEAR=(350)KWY.31X1.5-1.25D,1	1	\$91.35	\$91.35
142	3232915650	SET,SFT+GEAR=(350)KWY.31X1.5-1.25D,1	3	\$92.22	\$276.66
143	3232915650	SET,SFT+GEAR=(350)KWY.31X1.5-1.25D,1	1	\$92.22	\$92.22
144	3232922640	SET,SFT+GEAR=(350)KWY.25X1.25-1.00D	1	\$108.49	\$108.49
145	3232922640	SET,SFT+GEAR=(350)KWY.25X1.25-1.00D	1	\$108.49	\$108.49

LOT 1044 PARKER GEAR PUMPS FEB. 2010

	A	B	C	D	E
1	PART #	DESCRIPTION	QTY	UNIT REPLACEMENT COST	TOTAL REPLACEMENT COST
146	3233172905	PORT END ASSY	2	\$151.23	\$302.46
147	3235129204	SECOV/BSHG=(350)2-BLT,4.00PLT,SHORT	1	\$64.36	\$64.36
148	3235129204	SECOV/BSHG=(350)2-BLT,4.00PLT,SHORT	1	\$64.36	\$64.36
149	3237600571	B/C P350	7	\$116.15	\$813.05
150	3239110329	P350A242**AB22	2	\$585.45	\$1,170.90
151	3239112064	PGP350A242KEAB15-7	1	\$517.13	\$517.13
152	3239120288	PGP350B242IBAB22-7**AB07-1	10	\$1,055.38	\$10,553.80
153	3239210080	PGM350A897***EB*15-73*	10	\$720.51	\$7,205.10
154	3239210130	PGM350A800*VREB15-11*	6	\$643.55	\$3,861.30
155	3239210152	PGM350A842**EB20-11	4	\$639.53	\$2,558.12
156	3239218001	M350A842CTEB12-11	10	\$615.78	\$6,157.80
157	3243020100	PECOV=(330)7.0WX5.4HX2.5T,MACH-MOTOR	5	\$24.14	\$120.70
158	3243020100	PECOV=(330)7.0WX5.4HX2.5T,MACH-MOTOR	3	\$24.14	\$72.42
159	3245129203	SECOV/BSHG=(330)2-BLT-WING,4.00PLT,	3	\$50.56	\$151.68
160	3248205100	GEAR-HSG=(330)5.0WX5.9HX1.0T,MOTOR-	2	\$28.34	\$56.68
161	3248205100	GEAR-HSG=(330)5.0WX5.9HX1.0T,MOTOR-	1	\$28.34	\$28.34
162	3248205100	GEAR-HSG=(330)5.0WX5.9HX1.0T,MOTOR-	1	\$28.34	\$28.34
163	3248205100	GEAR-HSG=(330)5.0WX5.9HX1.0T,MOTOR-	1	\$28.34	\$28.34
164	3249115024	PGP330A542KEAB17-25	1	\$412.78	\$412.78
165	3249121617	PUMP	1	\$489.60	\$489.60
166	3249219022	PGM330A997VNEB12-25	2	\$303.17	\$606.34
167	3262907330	SET,SFT+GEAR=(315)13TX0.85D-SPLN,	1	\$57.98	\$57.98
168	3262910830	SET,SFT+GEAR=(315)KWY,..25X1.00-0.88	4	\$68.31	\$273.24
169	3263130377	PARKER PART	3	\$30.95	\$92.85
170	3268208100	GEAR-HSG=(315)4.2WX4.8HX1.3T,MOTOR-	1	\$22.37	\$22.37
171	3269110101	P315A296***AB20-65	8	\$292.83	\$2,342.64
172	3269219076	PGM315A996VNEB11-65	3	\$359.07	\$1,077.21
173	3269219098	PGM315A996VNEB18-65	2	\$313.70	\$627.40
174	3269219519	M315A996RQEB07-66	1	\$351.38	\$351.38
175	3297200100	M465-BC-BI/ROT	3	\$119.25	\$357.75
176	3297300100	BRG-CARR=(465)8.6WX7.0HX4.0T,MACH,	2	\$125.58	\$251.16
177	3319111441	PGP505A0020CJ2H2ND3D3B1B1B1	1	\$180.23	\$180.23
178	3339111012	P17A196BEAG-44-65	2	\$312.84	\$625.68
179	3339210043	MOTOR	1	\$322.09	\$322.09
180	3359200666	1MR190A8790	16	\$209.30	\$3,348.80
181	3559001154	RV/CAR/M350	2	\$114.58	\$229.16
182	3559001164	AC-ALINE/PORT	1	\$40.67	\$40.67
183	3559108128	PARKER PART	2	\$260.16	\$520.32
184	3759009022	AJ3009-93	3	\$34.99	\$104.97
185	3910381050	BRG,BALL=(CONV-078)1.38IDX3.15ODX0	40	\$17.10	\$684.00
186	3910381050	BRG,BALL=(CONV-078)1.38IDX3.15ODX0	17	\$17.10	\$290.70
187	3910381901	BRG,BOXED-ROLLER=3910381065	30	\$7.65	\$229.50
188	3910381901	BRG,BOXED-ROLLER=3910381065	20	\$7.65	\$153.00
189	3910381901	BRG,BOXED-ROLLER=3910381065	6	\$7.65	\$45.90
190	3910381901	BRG,BOXED-ROLLER=3910381065	3	\$7.65	\$22.95
191	3910482194	BUSHING	15	\$8.16	\$122.40
192	3911425032	STUD=0.62-11X0.62-11X16.25L,GR8,R-	11	\$7.55	\$83.05
193	3911781011	X10-2 KEY	4	\$0.33	\$1.32

	A	B	C	D	E
1	PART #	DESCRIPTION	QTY	UNIT REPLACEMENT COST	TOTAL REPLACEMENT COST
194	3911781018	X10-10 KEY	12	\$4.98	\$59.76
195	3911781019	X10-11 KEY	14	\$2.29	\$32.06
196	3911781019	X10-11 KEY	5	\$2.29	\$11.45
197	3911781030	KEY	139	\$5.48	\$761.72
198	3911781056	KEY,RECT=.25WX.88LX.38H,STL,RND-ENDS	12	\$2.37	\$28.44
199	3911781056	KEY,RECT=.25WX.88LX.38H,STL,RND-ENDS	10	\$2.37	\$23.70
200	3911781056	KEY,RECT=.25WX.88LX.38H,STL,RND-ENDS	10	\$2.37	\$23.70
201	3911781056	KEY,RECT=.25WX.88LX.38H,STL,RND-ENDS	4	\$2.37	\$9.48
202	3911781056	KEY,RECT=.25WX.88LX.38H,STL,RND-ENDS	3	\$2.37	\$7.11
203	3911801119	KIT,SERV=M350	1	\$68.80	\$68.80
204	3911803671	KIT	1	\$0.00	\$0.00
205	3911823131	CONNECTOR KIT	4	\$0.00	\$0.00
206	3912183019	AB1016 RETAINR	40	\$1.14	\$45.60
207	3912185901	THRPL,BOXED=(D)3912185001	219	\$16.02	\$3,508.38
208	3912185901	THRPL,BOXED=(D)3912185001	27	\$16.02	\$432.54
209	3912185901	THRPL,BOXED=(D)3912185001	14	\$16.02	\$224.28
210	3912185901	THRPL,BOXED=(D)3912185001	4	\$16.02	\$64.08
211	3912582030	SLEEVE	24	\$0.00	\$0.00
212	3912686017	PARKER PART	7	\$0.91	\$6.37
213	3912686017	PARKER PART	5	\$0.91	\$4.55
214	3912697003	RING,TOLERANCE=0.625IDX0.735ODX.49W	2	\$0.79	\$1.58
215	3912881119	VIBR.DAMPER	100	\$0.26	\$26.00
216	3912881267	ORING BUNA	12	\$1.80	\$21.60
217	3912881307	SEAL,O-R=01.171IDx.139WALL,BUNA-N,	110	\$0.53	\$58.30
218	3912881307	SEAL,O-R=01.171IDx.139WALL,BUNA-N,	24	\$0.53	\$12.72
219	3912881307	SEAL,O-R=01.171IDx.139WALL,BUNA-N,	14	\$0.53	\$7.42
220	3912881307	SEAL,O-R=01.171IDx.139WALL,BUNA-N,	8	\$0.53	\$4.24
221	3912881333	SEAL O-R=00.73IDX.103WALL	21	\$0.13	\$2.73
222	3912881333	SEAL O-R=00.73IDX.103WALL	18	\$0.13	\$2.34
223	3912881333	SEAL O-R=00.73IDX.103WALL	16	\$0.13	\$2.08
224	3912881333	SEAL O-R=00.73IDX.103WALL	4	\$0.13	\$0.52
225	3912881333	SEAL O-R=00.73IDX.103WALL	1	\$0.13	\$0.13
226	3912982001	F1391 CK VALVE	30	\$1.03	\$30.90
227	3913181007	BRG-SHIELD=3.14ODX1.50IDX.09W,	3	\$8.26	\$24.78
228	3913381009	JA1669 SHIELD	2	\$8.78	\$17.56
229	3913381009	JA1669 SHIELD	1	\$8.78	\$8.78
230	3913383002	TUBE=0.75ODX0.44IDX0.12LG,STL	53	\$2.14	\$113.42
231	3913383002	TUBE=0.75ODX0.44IDX0.12LG,STL	2	\$2.14	\$4.28
232	3913383002	TUBE=0.75ODX0.44IDX0.12LG,STL	2	\$2.14	\$4.28
233	3913383002	TUBE=0.75ODX0.44IDX0.12LG,STL	1	\$2.14	\$2.14
234	3913383003	TUBE=0.75ODX0.44IDX0.38LG,STL	2	\$2.32	\$4.64
235	3913383003	TUBE=0.75ODX0.44IDX0.38LG,STL	2	\$2.32	\$4.64
236	3913383003	TUBE=0.75ODX0.44IDX0.38LG,STL	2	\$2.32	\$4.64
237	3913383003	TUBE=0.75ODX0.44IDX0.38LG,STL	1	\$2.32	\$2.32
238	3913383044	MA1519-20	14	\$4.18	\$58.52
239	3913383044	MA1519-20	12	\$4.18	\$50.16
240	3913383044	MA1519-20	4	\$4.18	\$16.72
241	3913581854	SPR,EXT=1.50ODx7.00L,.25WD,MACH-LOOP	14	\$4.25	\$59.50

	A	B	C	D	E
1	PART #	DESCRIPTION	QTY	UNIT REPLACEMENT COST	TOTAL REPLACEMENT COST
242	3913581854	SPR,EXT=1.50ODx7.00L,,25WD,MACH-LOOP	2	\$4.25	\$8.50
243	3913782103	062 ADJ SHIM	70	\$1.80	\$126.00
244	3913782103	062 ADJ SHIM	49	\$1.80	\$88.20
245	3913782126	WASHER=1.02IDx1.50ODx.12THK,LEDLOY	8	\$0.61	\$4.88
246	3913782126	WASHER=1.02IDx1.50ODx.12THK,LEDLOY	2	\$0.61	\$1.22
247	0120615R	P16-115C-2N5	15	\$317.14	\$4,757.10
248	0120915R	P16-180C-2N5	1	\$334.06	\$334.06
249	C20-200-A-1-D-2	C20-200-A-1-D-2	2	\$243.88	\$487.76
250	D11AA1A	GEAR PUMP	24	\$107.98	\$2,591.52
251	D11AA2N110	GEAR PUMP	1	\$135.48	\$135.48
252	D14AA1D	GEAR PUMP	1	\$125.98	\$125.98
253	FD50B-BYED10-1-FED10BY	FD50B-BYED10-1-FED10BY	2	\$613.05	\$1,226.10
254	H25AB2A	GEAR PUMP	1	\$184.46	\$184.46
255	L88251863	COMM PISTON KIT	7	\$478.70	\$3,350.90
256	M15X905BEER1737	PUMP	1	\$297.00	\$297.00
257	M31A842BEAL20-30	MOTOR	1	\$501.79	\$501.79
258	MA3011-79	NUT	2	\$95.61	\$191.22
259	P315A193EJAB05-66	GEAR PUMP	1	\$161.76	\$161.76
260	P50A-342-BE-OR-22-25	P50A-342-BE-OR-22-25	2	\$211.16	\$422.32
261	P51A478BEAB25-11	PUMP	1	\$327.00	\$327.00
262					\$152,887.01
263	REPLACEMENT COSTS ARE SHOWN FOR <b>REFERENCE ONLY</b>				
264	THE SUPPLIER IS LOOKING FOR REASONABLE OFFERS ON ALL OR PART OF THIS LOT				
265	MILLIONS MORE AT 35% - 60% DISCOUNT ON OUR WEBSITE				
266	DOES <u>YOUR</u> VENDOR GIVE YOU EXTRA DISCOUNTS?? - <b>WE DO!!</b>				
267	<b>MAKE AN OFFER!!</b>				