

LOT 3316 OIL GEAR JUNE2015

	A	B	C	D
1	OIL GEAR	QTY	UNIT REPLACEMENT COST U.S.D.	TOTAL REPLACEMENT COST U.S.D.
2	PVV-250-B1SB-LDSF-P-1NN/F-SN-CN	1	\$6,850.00	\$6,850.00
3	PVV-250-B1SP-LSFS-P-1NN/F-SN-CN	3	\$6,850.00	\$20,550.00
4				
5				
6	REPLACEMENT COSTS ARE SHOWN FOR <u>REFERENCE ONLY</u>			
7	THIS LOT CAN BE PURCHASED IN WHOLE OR PART			
8	THE SUPPLIER IS LOOKING FOR REASONABLE OFFERS ON ALL OR PART OF THIS INVENTORY			
9	MILLIONS MORE AT 35% - 60% DISCOUNT ON OUR WEBSITE			
10	DOES YOUR VENDOR GIVE YOU EXTRA DISCOUNTS?? - WE DO!!			
11	ALL PRODUCT GUARANTEED!!			
12	MAKE OFFERS!!			