

LOT3424 AEROQUIP HOSE NOV2023

	A	B	C	D	E	F
1	MFG	PART NBR	QTY (FT)	LIST (FT)	UNIT REPLACEMENT COST USD	TOTAL REPLACEMENT COST USD
2	Aeroquip (100R5)	FC234-05	3400	\$29.19	\$11.27	\$38,318.00
3	High Temperature Fuel and Oil. Fire resistant USCG/MMT, NMMA/BIA.					
4	Aeroquip	FC699-04	42000	\$9.38	\$3.30	\$138,600.00
5	High Temperature Fuel and Oil. AQP lightweight engine hose.					
6	Aeroquip	FC699-08	2200	\$12.05	\$4.35	\$9,570.00
7	High Temperature Fuel and Oil. AQP lightweight engine hose.					
8						
9	TOTAL					\$186,488.00
10						
11	All hose has an AQP elastomer tube - NO SHELF LIFE LIMITS.					
12	Factory New on Reels					
13						
14	REPLACEMENT COSTS ARE SHOWN FOR REFERENCE ONLY					
15	THIS LOT CAN BE PURCHASED IN WHOLE OR PART					
16	MILLIONS MORE AT 35% - 60% DISCOUNT ON OUR WEBSITE					
17	DOES YOUR VENDOR GIVE YOU EXTRA DISCOUNTS?? - WE DO!!					
18	ALL PRODUCT GUARANTEED!!					
19	THE SUPPLIER IS LOOKING FOR REASONABLE OFFERS ON YOUR SELECTION OF THIS STOCK					
20	MINIMUM ORDERS APPLY					
21	MAKE AN OFFER!!					